1968 OCT 30 (19 228 3

\$Ø1824Z OCT 68 CITE	4929		DISTRIBUTI(25X1
PRIORITY PRIORITY	1020	CX CX	OFFICE
SUBJ: EVALUATION OF MISSION C16	920	Z	File 25X1
	RALL QUALITY OF THIS MISSI	IN TE	CABLE Sole
			1 1200 20 77570
THE MAJORITY OF THE ACQUISITIONS			SECUR.
A NEAR VERTICAL POSITION CAUSING	ROUND RESOLUTION AND PHOTO	3	1 7554
		VIMAREL	4 1551/APSD7
INTERPRETATION SUITABILITY ARE G		V T I.I H H-12-pa-	TERETON TO
15 PERCENT OF THE ENTIRE MISSION	•	***************************************	Ran
2. MISSION DATA:	TO A CONTRACTOR A LIAC CO		HOPAO
A. THE H CONFIGURATION CAM	ERA, UNIT NUMBER 1, WAS US	LD ON	The state of the s
MISSION C168C, FLOWN 20 OCT 1968			ILI
- · · · · · · · · · · · · · · · · · · ·	WAS USED THROUGHOUT THE EN		7 PRGD
	ING ANGLE CHANGES DURING T	1k	EGILA
ENTIRE MISSION.			
B. THE COMBINATION OF FILM	TYPE 50JH-2-2000 AND A WR	ATTEN 12	M
FILTER WAS USED THROUGHOUT THE M	ISSION. PROCESSING WAS AC	COMPLISH	EDSAST 25X1
3. ORIGINAL NEGATIVE:			PG
A. EXPOSURE: A SLIT VELOC	ITY OF 80 INCHES PER SECON	D WAIS US	
		<u> </u>	DIA-XX4
			SPAD
			DIA-AP
			25X1
·			UMX -25X
PAGE 2 4929 S E C R E T			25^
THROUGHOUT THE MISSION. THE EXP		UT.	
B. DENSITY AND CONTRAST AR		<del> </del>	-
C. IMAGE DEGRADATIONS: DOUBLE IMAGERY IS PRESENT ON FRAMES ADVANCE CY			
1977 THRU 2144. THE POINTING AN	IGLE DURING THESE EXPOSURES	WAS	SANITIZED
APPROXIMATELY 40 DEGREES. THE I	MAGERY WAS GOOD PRIOR TO (	NEAR	WITH TEXT
VERTICAL POSITION) AND AFTER (65	DEGREES POINTING ANGLE) T	HESE	

-- END OFMESSAGE --

EXPOSURES. PART OF THE LEFT FIDUCIAL WAS NOT IMAGED THROUGHOUT

FRAMES 623/624, 1310/1311, 1390/1391 AND 2594/2595.

E. OTHER: A FEW FRAMES ARE SMEARED DUE TO POINTING ANGLE

3. POSITIVES: THE PRINTING AND PROCESSING WERE GOOD. S E C R E T

D. PHYSICAL DEGRADATIONS: HEAT SPLICES ARE PRESENT BETWEEN

THE ENTIRE MISSION.

CHANGES.